VOL. VI. INDEX.

	Quarterly No.	Page No.
A		
A Gentle Hint	4	395
Annual Summary	4	497
Asbestos Roofing. Editorial	2	138
Automatic Control of Fire, The	2	149
Automatic Sprinklers as Life Savers. Editorial	4	393
Automatic Sprinklers, Discharge Characteristics of	1	48
Automobile Cleaning with Gasolene Spray	3	280
B		
Before and After	3	274
Boston Fire Hazards. Editorial	3	262
Brewery Fire Record	1	79
C		
Carpet Factories and Carpet Yarn Mills	2	173
Chimneys and Flues. Editorial	2	139
Coal Gas. Its Manufacture and Hazards	4	451
Coal Oil as a Fire Extinguishing Agent. Editorial	2	140
Color, Paint and Varnish Factories: No. 1, Page 67	3	302
Combined Sprinkler and Heating Systems	3	300
Conflagrations Occurring in 1911	1	21
Connections from City Water Mains to Sprinkler Systems and Standpipes	4	430
Corrosion of Iron and Steel Pipe	3	288
D		
Dip Tank Hazard. Fire Record	4	463
Direct Connections from City Water Mains to Sprinkler Systems and Standpipes	4	430
E		
Editorial: No. 1, Page 5; No. 2, Page 133; No. 3, Page 261	4	389
Electrolysis from Stray Electric Currents	4	438
Executive Committee Report. Editorial	1	6
F		
Factory Fire Perils, New York. Editorial	4	394
Fire Bug and the East Wind, The	2	164
Fire Causes: No. 1, Page 123; No. 2, Page 250; No. 3, Page 374	4	491
Fire Department Inspections. Editorial	4	133
Fire Engines, Motor. Efficiency and How to Determine It	3	283

VOL. VI. INDEX.

	Quarterly No.	Page No.
A		
A Gentle Hint	4	395
Annual Summary	4	497
Asbestos Roofing. Editorial	2	138
Automatic Control of Fire, The	2	149
Automatic Sprinklers as Life Savers. Editorial	4	393
Automatic Sprinklers, Discharge Characteristics of	1	48
Automobile Cleaning with Gasolene Spray	3	280
B		
Before and After	3	274
Boston Fire Hazards. Editorial	3	262
Brewery Fire Record	1	79
C		
Carpet Factories and Carpet Yarn Mills	2	173
Chimneys and Flues. Editorial	2	139
Coal Gas. Its Manufacture and Hazards	4	451
Coal Oil as a Fire Extinguishing Agent. Editorial	2	140
Color, Paint and Varnish Factories: No. 1, Page 67	3	302
Combined Sprinkler and Heating Systems	3	300
Conflagrations Occurring in 1911	1	21
Connections from City Water Mains to Sprinkler Systems and Standpipes	4	430
Corrosion of Iron and Steel Pipe	3	288
D		
Dip Tank Hazard. Fire Record	4	463
Direct Connections from City Water Mains to Sprinkler Systems and Standpipes	4	430
E		
Editorial: No. 1, Page 5; No. 2, Page 133; No. 3, Page 261	4	389
Electrolysis from Stray Electric Currents	4	438
Executive Committee Report. Editorial	1	6
F		
Factory Fire Perils, New York. Editorial	4	394
Fire Bug and the East Wind, The	2	164
Fire Causes: No. 1, Page 123; No. 2, Page 250; No. 3, Page 374	4	491
Fire Department Inspections. Editorial	4	133
Fire Engines, Motor. Efficiency and How to Determine It	3	283

Fire Loss Chart for the United States..... 3 276
Fire Loss, Comparative Statistics of..... 1 16
Fireman as an Educator, The..... 4 405
Fire Prevention Day. Editorial..... 2 134
Fireproofing of Cotton Goods..... 2 179
Fire-Resistive Buildings—Fire Record: No. 1, Page 107; No. 2, Page 246..... 3 361
Forest Fire Waste in Canada, The..... 2 167
Freezing of Fire Apparatus. Precautions Against..... 2 163

G

Gas, Illuminating, and Its Fire Hazard..... 4 441
Gas, Illuminating. Its Manufacture and Hazards..... 4 445
Gas Plants—Fire Record..... 4 476

H

Heating and Sprinkler Systems Combined..... 3 300
Height of Buildings, Regulating the..... 4 410
Horse Whips. Manufacturing Processes and Hazards.... 3 310
Hose, Bursting..... 2 142
Hose Couplings and Hydrant Fittings for Public Fire Service. Progress in the Adoption of..... 1 22
How to Detect Obstructions in Mains which Supply Fire Protection Systems..... 1 30

I

Iron and Steel Pipe. Relative Corrosion as Found in Service..... 3 288
Iron Hoops for Sprinkler Tanks..... 1 64
Italian Conditions. Editorial..... 1 9

J

Jamestown Conflagration..... 1 65

L

London's Fire Waste. Editorial..... 1 8
London's Post Office Fire. Editorial..... 2 135

M

Meters in Fire Lines. A Comparison of Efficiency..... 1 33
Miscellaneous Fires: No. 1, Page 121; No. 3, Page 365.. 4 485
Motor Pumping Engines. Efficiency and How to Determine It..... 3 283
Motor Spirit. Editorial..... 4 393

N

National Fire Prevention Congress. Editorial..... 4 390
Natural Gas Gasolene..... 3 292
Natural Gas Gasolene. Transportation of..... 3 296

O

Obstructions in Mains Which Supply Fire Protection Systems	1	30
Ohio State Building Code. Editorial	4	392

P

Paint Factories	3	302
Paper Box and Papeterie Factory Fire Record	3	335
Paper Box Manufacturing	3	328
Partial Sprinkler Equipments	3	263
Points of Interest From Fire Reports: No. 1, Page 125; No. 2, Page 253; No. 3, Page 377	4	494
Public Education: No. 1, Page 11; No. 2, Page 143; No. 3, Page 267	4	397
Pump House, A Model. Editorial	1	10

R

Railway Locomotives as Fire Engines. Editorial	2	136
Replacing Sprinkler Heads. Editorial	3	263
Roofing Materials. Their Comparative Cost	4	415

S

Shingle Roof Legislation. Editorial	2	137
Shoe Factory Fire Record	2	199
Spontaneous Ignition of Charcoal. Editorial	3	265
Spontaneous Combustion	2	188
Sprinkler Fire Tables, Annual	4	497
State Fire Prevention Associations' Committee Meeting	3	277
Stovepipes Through Partitions	3	264

T

Tank Failures, Sprinkler	1	50
Tanks, Wooden, Iron Hoops For	1	64

U

Unsatisfactory Sprinkler Fires: No. 1, Page 93; No. 2, Page 239; No. 3, Page 351	4	484

V

Vampires Three	4	404

W

Water Gas—Its Manufacture and Hazards	4	445
Waterworks Systems and the Fire Protection Problem	4	417
Wooden Buildings, Hazards of	4	396